


Fig. 1







Fig. 3






Fig. 4

5/35

Fig. 5




Fig. 6






Fig. 7



Center Device 82


Fig. 8



Portable Telephone 71




Fig. 9




10/35

Fig. 10




11/35

Fig. 11




Center Device 82

Fig. 12



13/35

Fig. 13



Portable Telephone 71

2025-06-26 14:00:00

Fig. 14





Fig. 15







Fig. 16




Fig. 17



18/35

Fig. 18



Portable Telephone 71

Fig. 19






Fig. 20




20/35

Fig. 21



21/35

Fig. 22



Portable Telephone 71

Fig. 23





Fig. 24






Fig. 25



25/35

Fig. 26






Fig. 27




On-Vehicle Device 151

Fig. 28




28/35

Fig. 29



29/35

Fig. 30



Center Device 82

Fig. 31






Fig. 32



32/35

Fig. 33



Portable Telephone 71

20050207-26628007



Fig. 34




Fig. 35




Fig. 36

